

PARKING LEVEL - ELECTRICAL PANELS & CMU WALL DAMAGE



PARKING LEVEL GATE AND DEBRIS, NOTE EDGE OF COLUMN




REAR OF BUILDING FIRST FLOOR WINDOWS



REAR LANAI OF BUILDING




PARKING LOT DAMAGE



PARKING LOT DAMAGE



GARAGE




INTERIOR HALLWAY



PARKING LOT DAMAGE




OFFICE TRAILER




OFFICE TRAILER



OFFICE TRAILER



OFFICE TRAILER



MISSING NPS LOGO



DISPLACED GUN




STAIRWAY




GUN BARREL PAINT SCOUR



STAIRWAY



FENCE DAMAGE




SAND CLEANUP



PAVED PARKING LOT



PAVED PARKING LOT




PAVED PARKING LOT



DISPLAY BOMB



GUARDRAIL SPACER BLOCKS



BRONZE RELIEF



BRONZE RELIEF



BRONZE RELIEF



BRONZE NAME MEMORIAL

ASAN POINT



CONCRETE SIDEWALK WASHOUT



FLAG POLE BASE W/MISSING LIGHT



SIDEWALK PLAQUE


ASAN POINT



CHILDRENS TABLE DAMAGE




SIGN DAMAGE & DEBRIS FIELD



MONUMENT DAMAGE




DEBRIS FIELD



MONUMENT MISSING PLAQUE



EMBANKMENT WASHOUT



EMBANKMENT WASHOUT

VEHICLE DAMAGE



DODGE RAM FLATBED

VEHICLE DAMAGE



FORD PASSENGER VAN


VEHICLE DAMAGE



CASE 580K BACKHOE




SIGN DAMAGE AND DEBRIS



MONUMENT DAMAGE

ASAN POINT



MONUMENT DAMAGE